

~~SECRET~~ NOFORN

BYE-1987-62  
cy 4 of 4

23 JUL 1962

MEMORANDUM FOR: Chief, Office of Special Activities /DDR

ATTENTION : Mr. Dave Sharp

SUBJECT : Technical Evaluation of Mission 3085

1. The HEPC evaluation of this mission was made from original recordings.

2. Performance of Recording Equipment:

All recording apparatus functioned properly during the reconnaissance.

3. Performance of Receiving Equipment:

a. P-band. Coherent analysis of the P-band data was extremely difficult because of intense vehicle associated 400 cps interference.

b. L-band. The usual interference related to camera activity was noted.

c. S-band. This receiver performed properly.

d. X-band. Satisfactory operation of the receiver prevailed throughout the flight.

25X1



Acting Chief  
Elint & Special Projects Division

25 YEAR RE-REVIEW

~~SECRET~~ NOFORN

GROUP 1  
Excluded from automatic  
downgrading and  
declassification

989-6  
CY 7-08-7

**SUBJECT: Technical Evaluation of Mission 3085**

**Distribution:**

Orig & 1 - Addressee  
1 - OSA/Intel/DDR  
1 - SPB/OSA/DDR  
2 - ESPD/SI  
2 - DPB/ESPD/SI

**OSI/ESPD/DPB:JHPearch:ldn:7141 (20 July 1962)**